



New Part Announcement

56-0200 PTO Slide Collar Quick Disconnect Repair Kit



The 56-0200 Slide Collar kit is a service part utilized to repair the tractor attaching yoke on all our metric 80 degree CV shaft assemblies. The following CV shaft assemblies would have this slide collar on the tractor end: 8-0200, 8-0201, 8-0202, 8-0203, 8-0204 and 8-0205. In addition to servicing the metric CV assemblies, this repair kit will fit all Benzi Di Terlizzi slide collar Q.D. yokes with 1.375-6 spline and 1.375-21 spline.

NEAPCO Components, LLC 740 Queen St. Pottstown, PA 19464

Phone: 800-821-2374

E-mail: hd@neapco.com

©2011 NEAPCO Components, LLC

Innovative Drivetrain Solutions™

9901298

Fax: 610-326-3857

Web site: www.neapco.com

06/2011

1